

AEROSTAR AIRCRAFT CORPORATION

SERVICE BULLETIN INDEX

DATE: 11/7/2000

PAGE 1

****For Reference Only**** Not to be used as a complete Official Service Bulletin Compliance Checklist. Refer to actual Service Bulletin for specific information, instructions, and specific serial numbers affected. Service Bulletin Index is provided as Reference Only and is not intended to be Official listings/descriptions of said publications. Contact Aerostar Aircraft Corporation's Technical Publications/Parts Department at 1-800-442-4242 or 208-762-0338 for Official Service Bulletin, Service Letter, and Airworthiness Directives information.

<u>NUMBER</u>	<u>REV DATE</u>	<u>SUBJECT</u>	<u>EFFECTIVITY</u>	<u>NOTES</u>
SB 600-1	6/16/69	Janitrol Heater Fitting Modification	60-0002 thru 60-0018	SUPERSEDED BY SL600-1R1
SB 600-1R1	7/15/69	Janitrol Heater Fitting Modification	60-0002 thru 60-0018 61-0001 thru 61-0013	
SB 600-2	6/25/69	Hydraulic System Modification	60-0002 thru 60-0015	OBSOLETE
SB 600-3	7/11/69	Nose Gear Retract Linkage Modification	60-0002 thru 60-0018 61-0003 thru 61-0009	
SB 600-4	7/16/69	Modification of Right and Left Wing Center Flap Tracks	60-0002 thru 60-0018 61-0002 thru 61-0007	
SB 600-5	7/17/69	Replacement of Cabin Floor Access Door	60-0002 thru 60-0019 61-0002 thru 61-0015	
SB 600-6	7/31/69	Installation of Modified Nose Wheel Strut Collar Assembly	60-0018, 60-0019, 61-0002, 61-0003, 61-0010 thru 61-0013, 61-0015	OBSOLETE
SB 600-7	9/5/69	Magneto Switch Modification	60-0002 thru 60-0004, 60-0006 thru 60-0023, 61-0002 thru 61-0015	
SB 600-8	9/8/69	Modification of Magneto "P" Leads and ADF Loop Antenna Cable Connector	All 600 and 601 Aerostars with ADF Operation Limitations Placard	
SB 600-9	9/25/69	Modified Induction Airbox Installation	61-0001 thru 61-0034	
SB 600-10	10/6/69	Brake Master Cylinder Modification	60-0002 thru 60-0026, 61-0002 thru 61-0016, 61-0019 thru 61-0023	
SB 600-11	10/10/69	Addition of Aft Oil Cooler Spacers	60-0001 thru 60-0026	
SB 600-12	10/16/69	Replacing and Safetying Turbocharger Rotary Actuator Bolts	61-0002 thru 61-0034	
SB 600-13	10/13/69	Replacement of Landing Gear Control Valve	60-0001 thru 60-0029, 61-0001 thru 61-0028	
SB 600-14	10/14/69	Installation of Elevator Trim Tab Control Split Switch	60-0001 thru 60-0028	
SB 600-15	10/21/69	Wing Rivet Inspection and Repair	60-0002 thru 60-0026, 61-0002 thru 61-0024	
SB 600-16	11/20/69	Main Landing Gear Lug Retaining Pin Installation	60-0002 thru 60-0031, 60-0033 thru 60-0037, 61-0002 thru 61-0033, 61-0035, 61-0036	
SB 600-17	1/29/70	Oxygen System Modification	61-0002 thru 61-0059	
SB 600-18	5/15/70	Installation of Wire Bundle Cover in Right Main Landing Gear Wheel Well	60-0001 thru 60-0056, 61-0001 thru 61-0070	
SB 600-19	5/15/70	Replacing Nose Gear Bushing Block Screws	60-0002 thru 60-0056, 61-0002 thru 61-0070	
SB 600-20	6/15/70	Replacing Oxygen System Overpressure Discharge Lines	61-0002 thru 61-0175	
SB 600-21	12/29/70	Replacement of the Main Landing Gear Sidebrace Assemblies	60-0001 thru 60-0056, 61-0001 thru 61-0070	REFERENCE AD 71-05-06
SB 600-22	6/30/70	Flap Operating Limitations and Flap Track Inspection	All Aerostar Models 600 and 601	SUPERSEDED BY SB600-22A

AEROSTAR AIRCRAFT CORPORATION

SERVICE BULLETIN INDEX

DATE: 11/7/2000

PAGE 2

****For Reference Only**** Not to be used as a complete Official Service Bulletin Compliance Checklist. Refer to actual Service Bulletin for specific information, instructions, and specific serial numbers affected. Service Bulletin Index is provided as Reference Only and is not intended to be Official listings/descriptions of said publications. Contact Aerostar Aircraft Corporation's Technical Publications/Parts Department at 1-800-442-4242 or 208-762-0338 for Official Service Bulletin, Service Letter, and Airworthiness Directives information.

<u>NUMBER</u>	<u>REV DATE</u>	<u>SUBJECT</u>	<u>EFFECTIVITY</u>	<u>NOTES</u>
SB 600-22A	6/30/70	Flap Operating Limitations and Flap Track Inspection	60-0001 thru 60-0056, 61-0001 thru 61-0070	REFERENCE AD 70-23-04
SB 600-23	11/23/70	Modification of Wing to Flap Attaching Structure	60-0001 thru 60-0056, 61-0001 thru 61-0070	REFERENCE AD 71-17-07
SB 600-24	11/23/70	Rework of the Alternator, Starter and Main Power Distribution Circuitry	60-0001 thru 60-0056, 61-0001 thru 61-0070	REFERENCE AD 71-10-02
SB 600-25	1/19/71	Inspection and Rework of Nose Landing Gear Trunnion Support Structure	60-0001 thru 60-0056, 61-0001 thru 61-0070	
SB 600-26	11/6/70	Relocation of Mike Jack, Earphone Jack, and Cabin Air Vent Controls	61-0001 thru 61-0070, Model 600: All Aircraft equipped with the Aerostar Model 601 oxygen system.	REFERENCE AD 70-25-09
SB 600-27	1/19/71	Modification of the Nose Landing Gear Steering System	60-0001 thru 60-0056, 61-0001 thru 61-0070	
SB 600-28	11/4/70	Rework of the Fuel Pressure Gage Vent Line	60-0001 thru 60-0056, 61-0001 thru 61-0070	REFERENCE AD 70-23-05
SB 600-29	8/23/71	Inspection and Modification of Throttle and Mixture Control Attachment at Engine Mounts	60-0001 thru 60-0056, 61-0001 thru 61-0070	
SB 600-30	2/9/71	Inspection and Replacement of the Turbocharger Support Brackets and Wastegate Warning Light Switch	61-0001 thru 61-0070	
SB 600-31	7/29/71	Corrosion Detection and Corrective Action	60-0001 thru 60-0056, 61-0001 thru 61-0070	SUPERSEDED BY SB902
SB 600-32	8/6/71	Inspection for Cracks in the Flap Track	All Model 600/601 Series Aircraft	
SB 600-33	1/12/74	Turbocharger Clamps	61-0001 thru 61-0070	
SB 600-34	7/27/73	Nose Landing Gear Steering Cylinder Retaining Bolt	60-0001 thru 60-0056, 61-0001 thru 61-0070	REVISED
SB 600-34R1	8/22/73	Nose Landing Gear Steering Cylinder Retaining Bolt	60-0001 thru 60-0017, 61-0003 thru 61-0009	
SB 600-35	8/28/73	Modification of Main Cabin Door Latch Installation	60-0001 thru 60-0056, 61-0001 thru 61-0070	
SB 600-36	7/9/73	Additional Insulation for Battery Mounting Clips, Inspection of Breaker Wiring and Starting Vibrator Cover Rework	60-0001 thru 60-0056, 61-0001 thru 61-0070	
SB 600-37	10/11/73	Engine 3-Way Gage	60-0001 thru 60-0056, 60-XXXX-057 thru 60-XXXX-065, 61-0001 thru 61-0070, 61-XXXX-071 thru 61-XXXX-080	
SB 600-38	10/16/73	Main Landing Gear Piston Assy. Inspection	60-0001-XXX thru 60-0056-XXX, 60-XXXX-057 thru 60-XXXX-064, 61-0001-XXX thru 61-0070-XXX, 61-XXXX-071 thru 61-XXXX-075	
SB 600-39	5/20/74	Engine Oil Line Inspection	61-0001-XXX thru 61-0070-XXX, 61-XXXX-071 thru 61-XXXX-081	
SB 600-40	7/8/74	Insulation Diode Overheat - 70 Amp Alternator	60-XXXX-064 thru 60-XXXX-073, 61-XXXX-076 thru 61-XXXX-083, 61P-XXXX-001 Only	
SB 600-41	7/11/74	Improved Hinge for Alternate Air Door in Air Induction Filter Housing	60-0001-XXX thru 60-0056-XXX, 60-XXXX-057 thru 60-XXXX-077	

AEROSTAR AIRCRAFT CORPORATION SERVICE BULLETIN INDEX

DATE: 11/7/2000

PAGE 3

****For Reference Only**** Not to be used as a complete Official Service Bulletin Compliance Checklist. Refer to actual Service Bulletin for specific information, instructions, and specific serial numbers affected. Service Bulletin Index is provided as Reference Only and is not intended to be Official listings/descriptions of said publications. Contact Aerostar Aircraft Corporation's Technical Publications/Parts Department at 1-800-442-4242 or 208-762-0338 for Official Service Bulletin, Service Letter, and Airworthiness Directives information.

<u>NUMBER</u>	<u>REV DATE</u>	<u>SUBJECT</u>	<u>EFFECTIVITY</u>	<u>NOTES</u>
SB 600-42	12/2/74	Aileron Bellcrank Bolt Inspection	60-0001-XXX thru 60-0056-XXX, 60-XXXX-057 thru 60-XXXX-070, 61-0001-XXX thru 61-0070-XXX, 61-XXXX-071 thru 61-XXXX-084	
SB 600-43	1/15/75	Engine Exhaust System Balance Tube Inspection and Support Installation	61-0001-XXX thru 61-0070-XXX, 61-XXXX-071 thru 61-XXXX-085, 61P-XXXX-001 thru 61P-XXXX-006	
SB 600-44	12/20/74	Cabin/Fuselage Drain Ports	61P-XXXX-001 thru 61P-XXXX-010	
SB 600-45	3/17/75	Inboard Flap Track Support	60-0001-XXX thru 60-0056-XXX, 60-XXXX-057 thru 60-XXXX-087, 61-0001-XXX thru 61-0070-XXX, 61-XXXX-071 thru 61-XXXX-090, 61P-XXXX-001 thru 61P-XXXX-014	REVISED
SB 600-45R1	4/21/75	Inboard Flap Track Support	60-0001-XXX thru 60-0056-XXX, 60-XXXX-057 thru 60-XXXX-087, 61-0001-XXX thru 61-0070-XXX, 61-XXXX-071 thru 61-XXXX-090, 61P-XXXX-001 thru 61P-XXXX-014	
SB 600-46	2/12/76	Remote Circuit Breaker Relays	ITEM 1 & 2: 60-0001-XXX thru 60-0056-XXX, 61-0001-XXX thru 61-0070-XXX, 60-XXXX-057 thru 60-XXXX-085, 61-XXXX-071 thru 61-XXXX-087, 62-0001-13, 61P-XXXX-001 thru 61P-XXXX-062 ITEM 1 ONLY: 60-XXXX-086 thru 60-XXX-0107, 61-XXXX-088 thru 61-XXX-0106, 61P-XXXX-013 thru 61P-XXXX-062	
SB 600-47	6/15/76	Replacement of Cleveland Main Wheel Assembly Bolts and Nuts	60-XXXX-075 thru 60-XXX-0110, 60-XXXX-085 thru 60-XXX-0107, 61P-XXXX-001 thru 61P-XXXX-071	
SB 600-48	6/8/76	Pilot Seat-Back Rest Attach Bolt	60-0130-057 thru 60-0285-108, 61-0132-071 thru 61-0281-107, 61P-0157-001 thru 61P-0284-066, Also the following individual aircraft: 60-0047-108 61-0059-112 60-0048-109 61-0063-117 60-0050-111 61-0064-119 60-0051-115 61-0065-121 60-0053-120 61-0066-122 60-0054-123 61-0068-126 61-0069-127 61-0070-129	
SB 600-49	6/15/76	Chafing of Oil Cooler Hose	61P-XXXX-022 thru 61P-XXX-077, 61P-XXX-001 thru 61P-XXX-022 with gross Weight Increase Modification, Option #93	
SB 600-50	6/17/76	Inspection of 920025-729 Oxygen Line Installation	61-XXXX-071 thru 61-XXXX-103, and 62-0001-013, 61P-XXX-001 thru 61P-XXX-058, Model 600 equipped with oxygen system installed prior to release date of this Service Bulletin.	

AEROSTAR AIRCRAFT CORPORATION SERVICE BULLETIN INDEX

DATE: 11/7/2000

PAGE 4

****For Reference Only**** Not to be used as a complete Official Service Bulletin Compliance Checklist. Refer to actual Service Bulletin for specific information, instructions, and specific serial numbers affected. Service Bulletin Index is provided as Reference Only and is not intended to be Official listings/descriptions of said publications. Contact Aerostar Aircraft Corporation's Technical Publications/Parts Department at 1-800-442-4242 or 208-762-0338 for Official Service Bulletin, Service Letter, and Airworthiness Directives information.

<u>NUMBER</u>	<u>REV DATE</u>	<u>SUBJECT</u>	<u>EFFECTIVITY</u>	<u>NOTES</u>
SB 600-51	10/14/76	Pilot and Copilot Seat Rework	60-0130-057 thru 60-0329-121, 61-0132-071 thru 61-0327-110, 61P-0157-001 thru 61P-0330-094, and the following individual A/C: 60-0047-108 61-0059-112 60-0048-109 61-0063-117 60-0050-111 61-0064-119 60-0051-115 61-0065-121 60-0053-120 61-0066-122 60-0054-123 61-0068-126 61-0069-127 61-0070-129	
SB 600-52	7/9/76	Fuel Selector Switch Knob	The following Serial Numbers manufactured prior to 1973: 60-0001-XXX thru 60-0056-XXX, 61-0001-XXX thru 61-0070-XXX The following Serial Numbers manufactured in 1973 and subsequent: 60-XXXX-057 thru 60-XXXX-129, 61-XXXX-071 thru 61-XXXX-0113, and 62-XXXX-013, 61P-XXXX-001 thru 61P-XXX-110	
SB 600-53	7/19/76	Center Fuel Tank, Fuel Probe Gasket	60-0284-107 thru 60-0310-115, 61-0307-109, 61P-0283-065 thru 61P-0315-085 With the following exceptions: 61P-0288-068; 61P-0291-070 61P-0300-076; 61P-0313-083; 61P-0314-084	
SB 600-54	8/30/76	Alternator Field Circuit Protection	PART I Applicable to the following A/C: a) A/C manufactured prior to 1973: 60-0001-003 thru 60-0056-128, 61-0001-004 thru 61-070-0129 b) A/C manufactured since 1973: 60-0130-057 thru 60-0189-085, 61-0132-071 thru 61-0186-087, and 62-0001-013, 61P-0157-001 thru 61P-0183-012 NOTE: Aircraft equipped with OEKO 20218 voltage regulators (which already incorporate circuit protection) are not affected by this Service Bulletin. PART II Applicable to the following A/C: 60-0190-086 thru 60-0355-127, 61-0191-088 thru 61-0352-114, 61P-0192-013 thru 61P-0354-109	
SB 600-55	8/30/76	Emergency Exit Door Rigging	All 601P S/N's 61P-0157-001 thru 61P-0330-094	
SB 600-56	8/26/76	Aileron Outboard Hinge Bolt Inspection	PART I A/C Manufactured prior to 1973: 60-0001-003 thru 60-0056-128, 61-0001-004 thru 61-0070-129 A/C Manufactured since 1973: 60-0130-057 thru 60-0329-121, 61-0132-071 thru 61-0327-110, 62-0001-013, 61P-0157-001 thru 61P-0330-094 PART II All models 600, 601, and 601P Aerostars	

AEROSTAR AIRCRAFT CORPORATION

SERVICE BULLETIN INDEX

DATE: 11/7/2000

PAGE 5

****For Reference Only**** Not to be used as a complete Official Service Bulletin Compliance Checklist. Refer to actual Service Bulletin for specific information, instructions, and specific serial numbers affected. Service Bulletin Index is provided as Reference Only and is not intended to be Official listings/descriptions of said publications. Contact Aerostar Aircraft Corporation's Technical Publications/Parts Department at 1-800-442-4242 or 208-762-0338 for Official Service Bulletin, Service Letter, and Airworthiness Directives information.

<u>NUMBER</u>	<u>REV DATE</u>	<u>SUBJECT</u>	<u>EFFECTIVITY</u>	<u>NOTES</u>
SB 600-57	10/27/76	Propeller Dome Charging Pressure Decal	All Aerostar Models, Airframe Sequence Number 0311 thru 0348 ONLY, and all A/C which have incorporated Hartzell Service Letter No. 91A (equipped with Hartzell HC-C3YR-2UF/FC 8468-8R Propellers).	
SB 600-58	11/23/76	Isolation Diode 70 Amp. Alternator Installation	Applies only to Aerostars equipped with 70 Amp. Alternators: 1. Airframe Sequence No. 0001 thru 0189, if modified per STC SA2336WE or STC SA2367WE 2. Airframe Sequence No. 0190 thru 0385.	SUPERSEDED BY SB600-58R1
SB 600-58R1	7/3/78	Isolation Diode 70 Amp. Alternator Installation	Aerostars equipped with 70 Amp. Alternators: 1. Airframe Sequence Number 0001 thru 0189, if modified per STC SA2336WE or STC SA2367WE. 2. Airframe Sequence Number 0190 thru 0448.	
SB 600-59	1/19/77	NLG Drag Brace Trunnion and Actuator Bracket Fastener Replacement	All Aerostar Models 600, 601, and 601P up to and including Airframe Sequence No. 0355.	REVISED
SB 600-59R1	12/22/77	NLG Drag Brace Trunnion and Actuator Bracket Fastener Replacement	All Aerostar Models up to and including Airframe Sequence Number 0385 as noted in instructions. AIRCRAFT IN COMPLIANCE WITH PREVIOUS RELEASE OF THIS SERVICE BULLETIN DATED JANUARY 19, 1977, ARE NOT AFFECTED BY THIS REVISION.	
SB 600-60	1/26/77	Starting System Wiring Revision	PART I All Aerostar Models 600, 601, and 601P up to and including Airframe Sequence No. 0189. PART II All Aerostar Models 600, 601, and 601P, with Airframe Sequence No. 0190 thru 0385 NOTE: Aircraft with Starting Wiring System Modified per SB600-24 are not affected by this Service Bulletin.	
SB 600-61	1/26/77	Main Cabin Door - Rod Fitting Inspection	All Aerostar Models 600 and 601 up to and including Airframe Sequence No. 0375.	
SB 600-62	2/16/77	Fuel Injector Attach Hardware Inspection	All Aerostar Models up to and including Airframe Sequence No. 0385	
SB 600-63	6/2/77	Century IV Autopilot NSD-360 Compass System	All Aerostar Models from Airframe Sequence No. 0240 up to and including 0368 equipped with Edo-Aire Mitchell Century IV Autopilot. All other Aerostars field retrofitted with the Century IV Autopilot are also affected regardless of Airframe Sequence Number.	
SB 600-64	6/28/77	Bendix FCS810 Flight Director 'V' Bar Power Source	All Aerostar Models Equipped with Bendix FCS810 Autopilot up to and including Airframe Sequence Number 0407.	
SB 600-65	6/29/77	Inspection of Pilot's Brake Lines	All Aerostar Models from Airframe Sequence No. 0356 thru 0407.	
SB 600-66	9/20/77	Seat Inspection/Rework	All Aerostar models up to and including airframe Sequence Number 0435.	

AEROSTAR AIRCRAFT CORPORATION

SERVICE BULLETIN INDEX

DATE: 11/7/2000

PAGE 6

****For Reference Only**** Not to be used as a complete Official Service Bulletin Compliance Checklist. Refer to actual Service Bulletin for specific information, instructions, and specific serial numbers affected. Service Bulletin Index is provided as Reference Only and is not intended to be Official listings/descriptions of said publications. Contact Aerostar Aircraft Corporation's Technical Publications/Parts Department at 1-800-442-4242 or 208-762-0338 for Official Service Bulletin, Service Letter, and Airworthiness Directives information.

<u>NUMBER</u>	<u>REV DATE</u>	<u>SUBJECT</u>	<u>EFFECTIVITY</u>	<u>NOTES</u>
SB 600-67	9/13/77	Aerosonic Encoding Altimeters	All Aerostar Models equipped with factory installed Aerosonic Encoding Altimeters, up to and including Airframe Sequence Number 0256, and all aircraft field retrofitted with Aerosonic Encoding Altimeters.	
SB 600-68	9/30/77	Cleveland Brake Disc Assembly Inspection	All Aerostar Models from Airframe Sequence No. 0171 up to and including 0455 and earlier Aerostars if equipped with Cleveland Wheels and Brakes per Option No. 78.	
SB 600-69	9/30/77	Seat Retainer Revision	All Aerostar Models prior to Airframe Sequence No. 0266.	
SB 600-70	12/9/77	Flight Manual Revisions and X-Feed Placard	All Aerostar Models up to and including Airframe Sequence Number 0474.	REFERENCE AD 77-26-04
SB 600-71	12/12/77	Low Fuel Warning	All Aerostar Models up to and including Airframe Sequence Number 0474. PART I affects A.S. No. 0001-0255 which are not equipped with a Low Fuel Warning Light per SL600-40 (TSA Opt. No. 16-1) PART II affects A.S. No. 0256-0474 which are equipped with a Low Fuel Warning Light adjusted to 17 +/-1 gallons of fuel remaining in fuselage tank.	REFERENCE AD 77-26-04
SB 600-72	1/13/78	Wing Tank Fuel Sumps	All Aerostar Models up to and including Airframe Sequence Number 0485.	
SB 600-73	4/28/78	Outboard Aileron Hinge Bolt Installation	All Piper Aerostar Models up to and including Airframe Sequence Number 0499.	
SB 600-74	7/3/78	Main Cabin Door Placards	All Aerostar Models 600, 601, and 601P up to and including Airframe Sequence Number 0545. PART I All unpressurized airplanes equipped with small "D" ring handle which rotates counter-clockwise to lock Model 600: 600-0001-003 thru 60-0056-128; 60-0130-057 thru 60-0304-113; except 60-0278-106. Model 601: 61-0001-004 thru 61-0070-129, except 61-0023-052, 61-0034-067, and 61-0060-113; 61-0132-071 thru 61-0301-108; 62-0001-013 PART II All pressurized airplanes. Model 601P: 61P-0157-001 thru 61P-0545-233; 61-0023-052, 61-0034-067 and 61-0060-113. PART III All pressurized airplanes equipped with large "D" ring handle which rotates clockwise to lock. Model 600: 60-0278-106; 60-0309-114 thru 60-0543-174 Model 601: 61-0307-109 thru 61-0537-133; 62-0001-013	SUPERSEDED BY SB908
SB 600-75	7/14/78	Main Landing Gear Scissors Assy. Inspection and Rework	All Aerostar Models 600, 601, and 601P up to and including Airframe Sequence Number 0554.	SUPERSEDED BY SB746C

AEROSTAR AIRCRAFT CORPORATION

SERVICE BULLETIN INDEX

DATE: 11/7/2000

PAGE 7

****For Reference Only**** Not to be used as a complete Official Service Bulletin Compliance Checklist. Refer to actual Service Bulletin for specific information, instructions, and specific serial numbers affected. Service Bulletin Index is provided as Reference Only and is not intended to be Official listings/descriptions of said publications. Contact Aerostar Aircraft Corporation's Technical Publications/Parts Department at 1-800-442-4242 or 208-762-0338 for Official Service Bulletin, Service Letter, and Airworthiness Directives information.

<u>NUMBER</u>	<u>REV DATE</u>	<u>SUBJECT</u>	<u>EFFECTIVITY</u>	<u>NOTES</u>
SB 600-75R1	12/22/78	Main Landing Gear Torque Link Inspection	All Aerostar Models 600, 601, and 601P up to and including Airframe Seq. Number 0554, IF equipped with 0.13 inch radius torque links (P/N 400076-501).	SUPERSEDED BY SB746C
SB 600-76	8/25/78	Fuel Quantity Indicator Selector Switch Installation	All Aerostar Model 600, 601, and 601P with Airframe Sequence Numbers 0150 through 0520.	
SB 600-77	9/6/78	Fuel Filler Cap Security	All Aerostar Models 600, 601, and 601P.	
SB 600-78	11/17/78	Fuel Line Between Fuel Pump and Fuel Injector	All Aerostar Models 600 up to and including Airframe Sequence Number 0322. All Aerostar Models 601 and 601P up to and including Airframe Sequence Number 0507.	REFERENCE AD 78-23-08
SB 600-79	12/22/78	Airplane Flight Manual Revisions/ Supplement and Fuel System Placards	All Aerostar Models 600, 601, and 601P which do not have the placards specified in this Service Bulletin and/or have not received Flight Manual Revisions or Flight Manual Supplement dated December 5, 1978.	
SB 600-80	4/6/78	Addition of Drain/ Ventilation Tubes to Engine Nacelle Firewall	All Aerostar Models 600, 601, and 601P up to and including Airframe Sequence No. 0659.	
SB 600-81	10/10/79	Three-Tank Fuel Quality Indicator	All Aerostar Models 600, 601, 601P Airframe Sequence No. 0001 through 0674.	REFERENCE AD 79-01-05
SB 600-82	9/24/79	Nose Landing Gear Support Structure Inspection/ Modification	Aerostar Models 600A, 601B, and 601P Airframe Sequence No. 0611 through 0714.	SUPERSEDED BY SB600-82A
SB 600-82A	12/15/79	Nose Landing Gear Support Structure Inspection/ Modification	Aerostar Models 600A, 601B, and 601P Airframe Sequence No. 0611 through 0714.	
SB 600-83	2/15/80	Nacelle Fairing Modification	All Aerostar Models 600, 601, and 601P up to and including Airframe Sequence No. 0799.	
SB 600-84	6/5/80	Engine Three-Way Gauge Inspection/Modification	Aerostar Models 600, 601, and 601P. Airframe Sequence Numbers 0600 through 0732, Inclusive.	
SB 600-85	6/5/80	Engine Wiring Harness Installation	All Aerostar Models 600, 601, and 601P up to and including Airframe Sequence No. 0714.	
SB 600-86	6/5/80	Bendix Starter Vibrator Cover Replacement	All Aerostar Models 600, 601, and 601P up to and including Airframe Sequence No. 0824.	
SB 600-87	9/18/81	King Autopilot (KFC-200) Wiring Rework and Modification	Aerostar Models 600, 601, and 601P with both King KFC-200 Autopilot and Dual Control Wheel accessories installed. Airframe Sequence Numbers 0339 through 0761, inclusive.	
SB 600-88	5/29/80	Horizontal and Vertical Stabilizer Attach Fitting Inspection and Attachment Hardware Replacement	All Aerostar Models 600, 601 and 601P up to and including Airframe Sequence No. 0807.	SUPERSEDED BY SB600-88A
SB 600-88A	7/29/80	Horizontal and Vertical Stabilizer Attach Fitting Inspection and Attachment Hardware Replacement	All Aerostar Models 600, 601 and 601P up to and including Airframe Sequence No. 0807.	
SB 630	12/14/78	Collins VIR-350 and VIR-351 Navigation Receiver Modification		SUPERSEDED BY SB630A
SB 630A	2/25/80	Collins VIR-350 and VIR-351 Navigation Receiver Modification		
SB 677	5/20/80	Publications for Aircraft Operations		

AEROSTAR AIRCRAFT CORPORATION

SERVICE BULLETIN INDEX

DATE: 11/7/2000

PAGE 8

****For Reference Only**** Not to be used as a complete Official Service Bulletin Compliance Checklist. Refer to actual Service Bulletin for specific information, instructions, and specific serial numbers affected. Service Bulletin Index is provided as Reference Only and is not intended to be Official listings/descriptions of said publications. Contact Aerostar Aircraft Corporation's Technical Publications/Parts Department at 1-800-442-4242 or 208-762-0338 for Official Service Bulletin, Service Letter, and Airworthiness Directives information.

<u>NUMBER</u>	<u>REV DATE</u>	<u>SUBJECT</u>	<u>EFFECTIVITY</u>	<u>NOTES</u>
SB 720	6/30/81	Required Changes to Engine Operation, Maintenance and Inspection Procedures. Modification to Manifold Fuel Nozzle Vent.		
SB 743	4/27/82	Flap Position Transmitter Arm Security		
SB 746		Main Landing Gear Torque Link Replacement		SUPERSEDED BY SB746C
SB 746A	5/2/86	Main Landing Gear Torque Link Replacement		SUPERSEDED BY SB746C
SB 746B	6/11/91	Main landing Gear Torque Link Replacement	All Aerostar Models	SUPERSEDED BY SB746C
SB 746C	9/15/92	Main Landing Gear Torque Link Replacement	All Aerostar Models	REFERENCE AD 93-13-08
SB 750	11/8/82	Propeller Control Cable Installation		
SB 755	2/14/83	Ignition Harness Routing Modification		
SB 756	3/8/83	Air Induction System Modification		
SB 757	6/20/83	Alternate Air Door Replacement		
SB 761	4/18/83	Turbocharger System oil Supply Hose Replacement		
SB 770	10/11/83	Airworthiness Directive 83-14-07		REFERENCE AD 83-14-07
SB 797		Fuel Port Restrictor Installation	All Aerostar 600, 601, 601P, 602P and 700P Models	SUPERSEDED BY SB797B
SB 797A	4/2/85	Fuel Port Restrictor Installation	All Aerostar 600, 601, 601P, 602P and 700P Models	SUPERSEDED BY SB797B
SB 797B	9/1/87	Fuel Port Restrictor Installation	All Aerostar 600, 601, 601P, 602P and 700P Models	
SB 798	12/11/84	'Turbo' Marking Removal		
SB 805	3/14/86	*TRW Hartzel Propeller Products Service Bulletin No. 142B ("O" Ring Deterioration)		SUPERSEDED BY SB805A
SB 805A	3/14/86	*TRW Hartzel Propeller Products Service Bulletin No. 142B ("O" Ring Deterioration)		
SB 815	1/3/86	Turbocharger Oil Supply Hose Security		
SB 818	2/25/86	Engine Exhaust System Inspection		
SB 832	4/18/86	Oil Separator Assembly Replacement		
SB 855	1/14/87	Use of Automobile Gasoline in Piper Aircraft		
SB 880	2/10/88	Elevator Down Spring Attach Point Modification	PA-60-600 Aerostar 600 60-0001-003 thru 60-0933-8161263 PA-60-601 Aerostar 601 61-0001-004 thru 61-0880-8162157 PA-60-601P Aerostar 601P 61P-0157-001 thru 61P-0860-8163455 PA-60-602P Aerostar 602P 62P-0750-8165001 thru 60-8365021 PA-60-700P Aerostar 700P 60-8423001 thru 60-8423025	SUPERSEDED BY SB880A

AEROSTAR AIRCRAFT CORPORATION

SERVICE BULLETIN INDEX

DATE: 11/7/2000

PAGE 9

****For Reference Only**** Not to be used as a complete Official Service Bulletin Compliance Checklist. Refer to actual Service Bulletin for specific information, instructions, and specific serial numbers affected. Service Bulletin Index is provided as Reference Only and is not intended to be Official listings/descriptions of said publications. Contact Aerostar Aircraft Corporation's Technical Publications/Parts Department at 1-800-442-4242 or 208-762-0338 for Official Service Bulletin, Service Letter, and Airworthiness Directives information.

<u>NUMBER</u>	<u>REV DATE</u>	<u>SUBJECT</u>	<u>EFFECTIVITY</u>	<u>NOTES</u>
SB 880A	4/14/88	Elevator Down Spring Attach Point Modification	PA-60-600 Aerostar 600 60-0001-003 thru 60-0933-8161263 PA-60-601 Aerostar 601 61-0001-004 thru 61-0880-8162157 PA-60-601P Aerostar 601P 61P-0157-001 thru 61P-0860-8163455 PA-60-602P Aerostar 602P 62P-0750-8165001 thru 60-8365021 PA-60-700P Aerostar 700P 60-8423001 thru 60-8423025	
SB 884	4/8/88	Lock Wiring of V-Band Couplings		
SB 898	8/1/90	Loss of Power in High Altitude Icing Conditions. Addition of Alternate Air Cable Locking Clips and Conversion of the Engine Fuel Injector Servo to add an Automatic Mixture Control.	Aerostar 700P 60-8423001 through 60-8423025	SUPERSEDED BY SB898A
SB 898A	8/1/90	Loss of Power in High Altitude Icing Conditions. Addition of Alternate Air Cable Locking Clips and Conversion of the Engine Fuel Injector Servo to add an Automatic Mixture Control.	Aerostar 700P 60-8423001 through 60-8423025	
SB 902	3/30/89	Corrosion Detection and Corrective Action	PA-60-600 Aerostar 600 60-0001 thru 60-0056 PA-60-601 Aerostar 601 61-0001 thru 61-0070, 62-0001-013	
SB 903	3/30/89	Structure Corrosion Inspection	PA-60-600 Aerostar 600 60-0130-057 thru 60-0941-8161263 PA-60-601 Aerostar 601 61-0132-071 thru 61-0880-8162157	
SB 908	5/23/89	Aerostar Cabin Door Inspection and Refinement	INSTRUCTION I 60-0001-003 thru 60-0933-8161262 61-0001-004 thru 61-0880-8162157 and 62-0001-013 61P-0157-001 thru 61P-0860-8163455 62P-0750-8165001 thru 62P-0932-8165055, and 60-8265001 thru 60-8365021 INSTRUCTION II 60-0001-003 thru 60-0056-128 60-0130-057 thru 60-0543-174 61-0001-004 thru 61-0531-133 and 62-0001-013 61P-0157-001 thru 61P-0545-233 61-0023-052, 61-0034-067 and 61-0060-113 INSTRUCTION III 60-0001-003 thru 60-0933-8161262 61-0001-004 thru 61-0880-8162157 and 62-0001-0130 61P-0157-001 thru 61P-0860-8163455 62P-0750-8165001 thru 62P-0932-8165055, and 60-8265001 thru 60-8365021 60-8423001 thru 60-8423018 INSTRUCTION IV 60-0001-003 THRU 60-0933-8161262 61-0001-004 THRU 61-0880-8162157	
SB 918	7/21/89	Induction Airbox and Upper Deck Reference Hose	61-0001-004 thru 61-0880-8162157 and 62-0001-013 61P-0157-001 thru 61P-0860-8163455 62P-0750-8165001 thru 62P-0932-8165055 and 60-8265001 thru 60-8365021 60-8423001 thru 60-8423025	

AEROSTAR AIRCRAFT CORPORATION

SERVICE BULLETIN INDEX

DATE: 11/7/2000

PAGE 10

****For Reference Only**** Not to be used as a complete Official Service Bulletin Compliance Checklist. Refer to actual Service Bulletin for specific information, instructions, and specific serial numbers affected. Service Bulletin Index is provided as Reference Only and is not intended to be Official listings/descriptions of said publications. Contact Aerostar Aircraft Corporation's Technical Publications/Parts Department at 1-800-442-4242 or 208-762-0338 for Official Service Bulletin, Service Letter, and Airworthiness Directives information.

<u>NUMBER</u>	<u>REV DATE</u>	<u>SUBJECT</u>	<u>EFFECTIVITY</u>	<u>NOTES</u>
SB 920	8/7/89	Engine Tailpipe Inspection and Addition of Fire Detection System	60-0001-003 thru 60-0933-8161262 61-0001-004 thru 61-0880-8162157 and 62-0001-013	REVISED
SB 920A	9/12/91	Engine Tailpipe Inspection and Addition of Fire Detection System	61P-0157-001 thru 61P-0860-8163455 62P-0750-8165001 thru 62P-0932-8165055 and 60-8265001 thru 60-8365021 60-8423001 thru 60-8423025	
SB 926	11/29/89	Hartzell Service Bulletin No. 165, Inspection for Cracks in Certain Three Blade "Y" Shank Aluminum Propeller Hubs	61-0001-004 thru 61-0880-8162157 and 62-0001-013 61P-0157-001 thru 61P-0860-8163455 62P-0750-8165001 thru 62P-0932-8165055 and 60-8265001 thru 60-8365021 60-8423001 thru 60-8423025	
SB 942	7/24/90	Forward Wing Spar Lower Cap Inspection Procedure	60-0001-003 thru 60-0933-8161262 61-0001-004 thru 61-0880-8162157 and 62-0001-013 61P-0157-001 thru 61P-0860-8163455 62P-0750-8165001 thru 62P-0932-8165055 and 60-8265001 thru 60-8365021 60-8423001 thru 60-8423025	
SB 950	2/27/91	Turbocharger Clamp Life Limit	61-0001-004 thru 61-0880-8162157 and 62-0001-013 61P-0157-001 thru 61P-0860-8163455 62P-0750-8165001 thru 62P-0932-8165055 and 60-8265001 thru 60-8365021 60-8423001 thru 60-8423025	SUPERSEDED BY SB600-119
SB 600-118	5/1/91	Installation of New Restricted Fuel Pump Vent Fittings in Engine Driven Fuel Pumps	All Aerostar Models 601, 601P, 602P, and 700P.	REFERENCE AD 91-08-07
SB 600-119	7/16/91	Turbocharger Clamp Life Limit and Replacement	All turbocharged Aerostar Models 601, 601P, 602P and 700P	
SB 600-120	8/5/91	Replacement of Throttle, Prop, and Mixture Control Cables	All Aerostars up to and including Airframe Sequence Number 0933.	
SB 600-121	9/12/91	Nose Gear Drag Brace Spring and Piston Replacement	Aerostar 600's with Option #199 60-0001-003 thru 60-0608-7961195 Aerostar 600 60-0614-7961196 thru 60-0933-8164262 Aerostar 601's with Option #199 61-0001-004 thru 61-0605-7962136 Aerostar 601 61-0611-7962137 thru 61-0880-8162157 Aerostar 601P's with Option #199 61P-0157-001 thru 61P-0610-7963274 Aerostar 601P 61P-0612-7963275 thru 61P-0859-8163455 Aerostar 602P 62P-0750-8165001 thru 60-8365021 Aerostar 700P 60-8423001 thru 60-8423025	SUPERSEDED BY SB600-128
SB 600-122	10/3/91	Inspection and Limits for Wear in 600050 Series Control System Pushrods	All Aerostar Models	
SB 600-123	11/8/91	Inspection of Front Exhaust Manifold Assemblies	All Turbocharged Aerostar Models 601, 601P, 602P, and 700P	

AEROSTAR AIRCRAFT CORPORATION

SERVICE BULLETIN INDEX

DATE: 11/7/2000

PAGE 11

****For Reference Only**** Not to be used as a complete Official Service Bulletin Compliance Checklist. Refer to actual Service Bulletin for specific information, instructions, and specific serial numbers affected. Service Bulletin Index is provided as Reference Only and is not intended to be Official listings/descriptions of said publications. Contact Aerostar Aircraft Corporation's Technical Publications/Parts Department at 1-800-442-4242 or 208-762-0338 for Official Service Bulletin, Service Letter, and Airworthiness Directives information.

<u>NUMBER</u>	<u>REV DATE</u>	<u>SUBJECT</u>	<u>EFFECTIVITY</u>	<u>NOTES</u>
SB 600-124	9/28/92	Replacement of Existing Fuel and Oil Hoses Behind the Firewalls With Fire Resistant Hoses	All Aerostar Models except those already equipped with fireproof type fuel and oil pressure sense hoses and fireproof type main fuel hoses installed in accordance with the following STC's: SA980NW, SA1658NM, or SA2612NM.	
SB 600-125	12/4/92	Addition of Fuel Spillage Placards	All Aerostar Models	
SB 600-126	12/7/92	Alteration of Existing Wing Fuel Tank Vent System	All Aerostar Models produced before 1992	
SB 600-127	1/18/94	Installation of Wastegate Actuator Oil Filters	Aerostar 601's with Option #196 61-0001-004 thru 61-0334-111 Aerostar 601 61-0342-112 thru 61-0880-8162157 Aerostar 601P 61P-0157-001 thru 61P-0860-8163455 Aerostar 602P 62P-0750-8165001 thru 60-8365021 Aerostar 700P 60-8423001 thru 60-8423025	
SB 600-128	9/12/91	Nose Gear Lower Drag Brace Link Assembly Replacement	Aerostar 600's with Option #199 60-0001-003 thru 60-0608-7961195 Aerostar 600 60-0614-7961196 thru 60-0933-8164262 Aerostar 601's with Option #199 61-0001-004 thru 61-0605-7962136 Aerostar 601 61-0611-7962137 thru 61-0880-8162157 Aerostar 601P's with Option #199 61P-0157-001 thru 61P-0610-7963274 Aerostar 601P 61P-0612-7963275 thru 61P-0859-8163455 Aerostar 602P 62P-0750-8165001 thru 60-8365021 Aerostar 700P 60-8423001 thru 60-8423025	REFERENCE AD 92-13-01
SB 600-129	4/29/94	Replacement of Turbocharger Oil Supply Relief/Shut Off Valve Part Number 532A-2MP-21 or 520A-2MP-21, Piper Code Number 491-917, and outlet fitting.	All Aerostar Models 601, 601P, 602P, and 700P	SUPERSEDED BY SB600-129A
SB 600-129A	1/16/95	Replacement of Turbocharger Oil Supply Relief Valves and Outlet Fittings	All Aerostar Models 601, 601P, 602P, and 700P	
SB 600-130	9/26/95	Inspection of Fuselage Horizontal Stabilizer Attach Fittings	All Aerostar Models with Airframe Numbers 0001 thru 0849	REFERENCE AD 95-23-11
SB 600-131	6/14/96	Inspection of Turbocharger Oil Scavenge Pump	All Turbocharged Aerostar Models; 601, 601P, 602P, 700P	SUPERSEDED BY SB600-131A
SB 600-131A	1/10/98	Replacement of Turbocharger Oil Scavenge Pumps	All Turbocharged Aerostar Models; 601, 601P, 602P, 700P	
SB 600-132	9/3/97	Inspection of 55% Upper Spar Cap	All Aerostar Models	
SB 600-133	6/3/98	Improved Attachment of Wing Aileron Bellcrank Bracket	All Aerostar Models	SUPERSEDED BY SB600-133R1
SB 600-133R1	7/6/98	Improved Attachment of Wing Aileron Bellcrank Bracket	All Aerostar Models	
SB 600-134	11/30/99	Main Landing Gear Lower Side Brace	All	SUPERSEDED BY SB600-134A
SB 600-134A	3/31/2000	Main Landing Gear Lower Side Brace	All Aerostar PA-60 Models of All Serial Numbers Thru Airframe 1026 (Aircraft Manufactured Prior to 1985)	

AEROSTAR AIRCRAFT CORPORATION SERVICE BULLETIN INDEX

DATE: 11/7/2000

PAGE 12

****For Reference Only**** Not to be used as a complete Official Service Bulletin Compliance Checklist. Refer to actual Service Bulletin for specific information, instructions, and specific serial numbers affected. Service Bulletin Index is provided as Reference Only and is not intended to be Official listings/descriptions of said publications. Contact Aerostar Aircraft Corporation's Technical Publications/Parts Department at 1-800-442-4242 or 208-762-0338 for Official Service Bulletin, Service Letter, and Airworthiness Directives information.

<u>NUMBER</u>	<u>REV DATE</u>	<u>SUBJECT</u>	<u>EFFECTIVITY</u>	<u>NOTES</u>
SB 600-135	11/30/99	Possible Corrosion - Wing Fuel Pipe Assembly	All	
SB 600-136	9/15/2000	Wing Attach Fittings	All Aerostar PA-60 Models of All Serial Numbers Thru Airframe 1026 (Aircraft Manufactured Prior to 1985)	